

2021年3月25日

お客様各位

New Zealand 向け中古自動車の新基準項目 – ITS Connect

ニュージーランド政府 NZ Transport Agency (NZTA) より、ニュージーランドへ輸入される中古自動車の規制に対し新しい基準項目が発表されております。

日本車の一部（主にトヨタ、レクサス）に搭載されている ITS Connect システムは 760MHz の周波数で信号を送受信し機能しますが、NZ の無線通信法（電波法）では、この周波数で動作するデバイスを輸入、及び操作することが違法となります。（NZ では通信用に国が管理する周波数の為）

新基準項目では、2021年4月1日以降に検査を受ける全車両を対象として、当該車両が ITS Connect 搭載の場合、お客様自身にてディーラーへ撤去作業のご相談後、車両をお持ち込みの上作業を行っていただき、ITS Connect システムが撤去された証明（撤去依頼の車体番号が記載された領収書や請求書なども可）の提出が義務となります。

4月1日以降に検査された車両で、ITS Connect 搭載の対象車両は、ディーラーでの撤去作業と証明書なしでの輸出は禁止となりますので、ご留意の程よろしくお願い申し上げます。

尚、弊社では撤去が行えないこと、またディーラーでの撤去に関しての一切の責任を負いかねますので、予めご了承くださいませようお願い申し上げます。

ITS Connect 搭載可否の検査が必要な車両

Make	Model	Vehicle Year	Most likely fitment
Lexus	RX	2016+	メーカーオプション
Lexus	LS	2018+	全てのモデルに標準装備
Lexus	RX	2018+	上級モデルに標準装備, 他はオプション装備
Lexus	ES	2018+	上級モデルに標準装備, 他はオプション装備
Lexus	UX	2018+	上級モデルに標準装備, 他はオプション装備
Toyota	Prius PHV	2016+	メーカーオプション
Toyota	Prius	2016+	メーカーオプション
Toyota	Crown	2016+	メーカーオプション
Toyota	Harrier	2018+	メーカーオプション
Toyota	Alphard	2018+	メーカーオプション
Toyota	Vellfire	2018+	メーカーオプション
Toyota	Noah	2018+	ディーラーオプション

Our Valued Customers,

Ref: NZTA Announcement – ITS Connect system – Export Vehicles to New Zealand Regulation

NZ Transport Agency (NZTA) has announced that **all used vehicles equipped with ITS Connect system cannot be imported to New Zealand from 1 April 2021.**

ITS Connect system, mostly equipped on *Toyota and Lexus* cars, operates in the 760 MHz frequency of radio spectrum which is reserved for telecommunications in New Zealand. Under the Radio Communications Act 1989, it is illegal to import or operate a device operating on this frequency in New Zealand.

Therefore, from 1 April 2021, it will be necessary to remove the device by taking units to dealer of manufacturer. To prove the device is removed, please ask the dealer to issue a certificate (a receipt or invoice for removing the device with the VIN number is also acceptable) to inform to NZTA. Any units to be exported to NZ with an ITS Connect system equipped (or had equipped) have to be flagged and informed to NZTA in advance.

Please notice that ATJ has no authorities to remove the device. At the same time, ATJ does not carry any responsibilities for matters related with removing the device. Please contact your local Toyota (or Lexus) dealer directly for further details.

Vehicles that must be inspected for ITS Connect

Make	Model	Vehicle Year	Most likely fitment
Lexus	RX	2016+	Manufacturer option
Lexus	LS	2018+	Equipped standard in all variants
Lexus	RX	2018+	Equipped standard in advanced variants, likely option in others
Lexus	ES	2018+	Equipped standard in advanced variants, likely option in others
Lexus	UX	2018+	Equipped standard in advanced variants, likely option in others
Toyota	Prius PHV	2016+	Manufacturer option
Toyota	Prius	2016+	Manufacturer option
Toyota	Crown	2016+	Manufacturer option
Toyota	Harrier	2018+	Manufacturer option
Toyota	Alphard	2018+	Manufacturer option
Toyota	Vellfire	2018+	Manufacturer option
Toyota	Noah	2018+	Dealer option

For your reference, please check for more specific information on the NZTA website;

Technical Bulletin for ITS Connect (ITS Connectについての技術報告書)

https://vehicleinspection.nzta.govt.nz/_data/assets/pdf_file/0020/79310/TB-3-Vehicles-fitted-with-ITS-Connect.pdf



General introduction of ITS Connect (ITS Connectの概要)

https://www.itsconnect-pc.org/en/about_its_connect/



<https://toyota.jp/technology/safety/itsconnect/>



<https://global.toyota/en/detail/9676551>



対象モデル

Make	Model	Model Code
Lexus	ES	6AA-AXZH10
Lexus	LS	DAA-UUF45
Lexus	LS	DBA-USF41
Lexus	LS	DBA-USF46
Lexus	LS	DAA-UUF46
Lexus	LS	DBA-USF40
Lexus	LS	DBA-USF45
Lexus	LS	DBA-VXFA50
Lexus	LS	DBA-VXFA55
Lexus	LS	DAA-GVF50
Lexus	LS	DAA-GVF55
Lexus	LS	6AA-GVF50
Lexus	LS	6AA-GVF55
Lexus	RX	DBA-GGL10W
Lexus	RX	DBA-GGL15W
Lexus	RX	DAA-GYL10W
Lexus	RX	DAA-GYL15W
Lexus	RX	DAA-GYL16W
Lexus	RX	DBA-AGL10W
Lexus	RX	DAA-GYL20W
Lexus	RX	DAA-GYL25W
Lexus	RX	DBA-AGL20W
Lexus	RX	DBA-AGL25W
Lexus	RX	DAA-GYL26W
Lexus	RX	6AA-GYL20W
Lexus	RX	6AA-GYL25W
Lexus	RX	6AA-GYL26W
Lexus	RX	3BA-AGL20W
Lexus	RX	3BA-AGL25W
Lexus	UX	6BA-MZAA10
Lexus	UX	6AA-MZAH10
Lexus	UX	6AA-MZAH15
Toyota	Alphard	DBA-AGH30W
Toyota	Alphard	DBA-GGH30W
Toyota	Alphard	DBA-AGH35W
Toyota	Alphard	DBA-GGH35W
Toyota	Alphard	DAA-AYH30W
Toyota	Alphard	3BA-AGH30W
Toyota	Alphard	3BA-AGH35W

Toyota	Alphard	3BA-GGH30W
Toyota	Alphard	3BA-GGH35W
Toyota	Alphard	6AA-AYH30W
Toyota	Crown	DAA-AWS210
Toyota	Crown	DAA-AWS211
Toyota	Crown	DBA-GRS210
Toyota	Crown	DBA-GRS214
Toyota	Crown	DBA-GRS211
Toyota	Crown	DAA-GWS214
Toyota	Crown	DAA-AWS215
Toyota	Crown	DBA-ARS210
Toyota	Crown	3BA-ARS220
Toyota	Crown	6AA-AZSH20
Toyota	Crown	6AA-AZSH21
Toyota	Crown	6AA-GWS224
Toyota	Harrier	DBA-ZSU60W
Toyota	Harrier	DBA-ZSU65W
Toyota	Harrier	DAA-AVU65W
Toyota	Harrier	DBA-ASU60W
Toyota	Harrier	DBA-ASU65W
Toyota	Harrier	6BA-MXUA80
Toyota	Harrier	6BA-MXUA85
Toyota	Harrier	6AA-AXUH80
Toyota	Harrier	6AA-AXUH85
Toyota	Noah	DBA-ZRR80G
Toyota	Noah	DBA-ZRR85G
Toyota	Noah	DAA-ZWR80G
Toyota	Noah	DBA-ZRR80W
Toyota	Noah	DBA-ZRR85W
Toyota	Noah	DAA-ZWR80W
Toyota	Noah	3BA-ZRR80G
Toyota	Noah	3BA-ZRR80W
Toyota	Noah	3BA-ZRR85G
Toyota	Noah	3BA-ZRR85W
Toyota	Noah	6AA-ZWR80G
Toyota	Noah	6AA-ZWR80W
Toyota	Prius	DLA-ZVW35
Toyota	Prius	DAA-ZVW30
Toyota	Prius	DAA-ZVW40W
Toyota	Prius	DAA-ZVW41W

Toyota	Prius	DAA-ZVW50
Toyota	Prius	DAA-ZVW55
Toyota	Prius	DAA-ZVW51
Toyota	Prius	DLA-ZVW52
Toyota	Prius	6AA-ZVW51
Toyota	Prius	6AA-ZVW55
Toyota	Prius	6LA-ZVW52
Toyota	Velfire	DBA-AGH30W
Toyota	Velfire	DBA-GGH30W
Toyota	Velfire	DBA-AGH35W
Toyota	Velfire	DBA-GGH35W
Toyota	Velfire	DAA-AYH30W
Toyota	Velfire	3BA-AGH30W
Toyota	Velfire	3BA-AGH35W
Toyota	Velfire	3BA-GGH30W
Toyota	Velfire	3BA-GGH35W
Toyota	Velfire	6AA-AYH30W